



For complete documentation this drawing should be accompanied by SolidWorks or Step file

Drw: rosnmar 10.10.2018		Size, std:		Tolerance:  ±0,1	Geometric tolerance symbols acc. ISO1101 General tolerance symbols acc. ISO2768 Surface roughness symbols acc. ISO1302			
Chk:		Material:						
App:		Finish:						
Prod:				Lock 500 assembly				
Sheet: 1/1		Size: <b>A3</b>						
Scale: 1:1		Metric: mm		<div>Part number: <i>Lock 500</i></div>				
Mass: 156.81								
						Ver	Rev	
						0	0	